



Kensington K70990WW Orbit Wireless Trackball with Scroll Ring User Guide

[Home](#) » [Kensington](#) » Kensington K70990WW Orbit Wireless Trackball with Scroll Ring User Guide 


Contents

- [1 Compatibility](#)
- [2 FCC STATEMENT :](#)
- [3 Documents / Resources](#)
- [4 Related Posts](#)

Kensington®




Orbit® Wireless Trackball with Scroll Ring
Orbit® Wireless Trackball with Scroll Ring – White
Orbit® Wireless Trackball with Scroll Ring – Space Grey



kensington.com/register


1




2




OFF



:







:





:

OFF





Scroll ring



Compatibility



IMPORTANT: Computer User Health Information

Use of a keyboard, mouse, or trackball may be linked to serious injuries or discomfort. Recent medical research of occupational Injuries has linked normal, seemingly harmless activities as a potential cause of Repetitive Stress Injuries ("RSI"). Many factors may be linked to the occurrence of RSI, including a person's own medical and physical condition,

overall health, and how a person positions and uses his or her body during work and other activities (including use of a keyboard, mouse, or trackball). Some studies suggest that the amount of time a person uses a keyboard,

mouse, or trackball may also be a factor. Consult a qualified health professional for any questions or concerns you may have about these risk factors.

When using a keyboard, mouse, or trackball, you may experience occasional discomfort in your hands, arms, shoulders, neck, or other parts of your body. However, if you experience symptoms such as persistent or recurring discomfort, pain, throbbing, aching, tingling, numbness, burning sensation, or stiffness, even if such symptoms occur while you are not working at your computers. **DO NOT IGNORE THESE WARNING SIGNS. PROMPTLY SEE A QUALIFIED HEALTH PROFESSIONAL.** These symptoms can be signs of sometimes permanently disabling RSI disorders of the nerves, muscles, tendons, or other parts of the body.



CAUTION: Never spray liquid cleaner directly on the trackball

RF TECHNICAL SPECIFICATION

Operating Frequency Range: 24022480MHz

Maximum RF Output Power: 0dBm

SAFETY AND USAGE GUIDELINES

1. In the absence of proper operation and if customer-initiated troubleshooting is unsuccessful, switch off the device and contact Kensington technical support: www.kensington.com
2. Do not disassemble the product or expose it to liquid, humidity, moisture, or temperatures outside the specified operating ranges of 0° C (32° F) to 40° C (104° F).
3. If your product is exposed to out-of-range temperatures, switch it off and allow the temperature to return to the normal operating range.
4. When the batteries are dead, replace all batteries from the product at the same time with the correct size and type of batteries.
5. Keep batteries away from children.
6. Do not misuse, damage, disassemble or modify the batteries



www.kensington.com/support

FCC STATEMENT :

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) This device may not cause harmful interference, and
- (2) This device must accept any interference received, including interference that may cause undesired operation.

Warning: Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

NOTE: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates uses and can radiate radio frequency energy and, if not installed

and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a

particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the

user is encouraged to try to correct the interference by one or more of the following measures: Reorient or relocate the receiving antenna. Increase the separation between the equipment and receiver. Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.

Consult the dealer or an experienced radio/TV technician for help.

RF warning statement:

The device has been evaluated to meet general RF exposure requirements. The device can be used in portable

exposure conditions without restriction.

This device complies with Industry Canada licence-exempt RSS standard(s). Operation is subject to the following two conditions:

(1) this device may not cause interference, and

(2) this device must accept any interference, including interference that may cause undesired operation of the device.”



**R-C-KCP-M01554-M, R-C-KCP-M01497-D
M01554-M, M01497-D
Kensington Computer Products Group**



**Kensington Computer Products Group
A Division of ACCO Brands**


1500 Fashion Island Blvd, 3rd Floor
San Mateo, CA 94404, USA

Importer:

LEITZ ACCO Brands GmbH & Co KG
Siemensstraße 64
70469 Stuttgart
Germany

**K70990 / K70991 / K70992 / K70993 / K72675
901- 7300-01**

Documents / Resources



[Kensington K70990WW Orbit Wireless Trackball with Scroll Ring](#) [pdf] User Guide
M01554-M, M01554M, GV3M01554-M, GV3M01554M, K70990WW Orbit Wireless Trackball with Scroll Ring, Orbit Wireless Trackball with Scroll Ring